

NO FOG CLOTH



Reusable NO FOG CLOTH helps rejuvenate the original anti-fog lens coating. Packaged in cases of 25.

For maximum fog protection use the NO FOG CLOTH on your eyewear before each use.

To apply, moisten the lens surface with a light breath and wipe with NO FOG CLOTH. Let dry. If necessary, buff streaks with a dry cotton cloth.

Also use NO FOG CLOTH on ESS RX Inserts and/or eyeglasses worn inside the goggles.

Tightly seal the plastic bag when storing.

The NO FOG CLOTH can be refreshed with a few drops of water to keep moist.

Pacific part number for ordering # A104186



Pacific Helmets (NZ) Ltd

Ph +64 (6) 344 5019, Fax +64 (6) 344 5376

E-mail: sales@pacifichelmets.com

www.pacifichelmets.com

